

No.12

36p.



AB

N64-17684\*

CODE-1

CB-56004

Effect of NUCLEAR RADIATION on Materials at

CRYOGENIC

TEMPERATURES

OTS PRICE

XEROX

\$

3.60 ph

MICROFILM

\$

1.28 ref.

NASA CR 56004

LNP

# Quarterly Report

OCT 1963-

DEC 1963

to NASA

LOCKHEED NUCLEAR PRODUCTS

(NASA ER-56004; *title suppl.* ER-6793) OTS: \$3.60 ph, \$1.28 mf

**QUARTERLY  
PROGRESS  
REPORT  
No.12**

October 1963 through December 1963

*title*  
**Effect of Nuclear Radiation on materials  
at Cryogenic Temperatures**

PREPARED UNDER

**National Aeronautics/Space Administration**

(NASA **Contract NASw-114**)

*C.A. Schwantek [1963] 36 p orig*


APPROVED BY

*C. A. Schwantek*

NASA CRYOGENICS  
PROJECT MANAGER

*1438472*

Lockheed-Georgia Company



A Division of Lockheed Aircraft Corporation

*Marietta, Ga.*

If this document is supplied under the requirements of a United States Government contract, the following legend shall apply unless the letter U appears in the coding box:


This data is furnished under a United States Government contract and only those portions hereof which are marked (for example, by circling, underscoring or otherwise) and indicated as being subject to this legend shall not be released outside the Government (except to foreign governments, subject to these same limitations), nor be disclosed, used, or duplicated, for procurement or manufacturing purposes, except as otherwise authorized by contract, without the permission of Lockheed-Georgia Company, A Division of Lockheed Aircraft Corporation, Marietta, Georgia. This legend shall be marked on any reproduction hereon in whole or in part.

The "otherwise marking" and "indicated portions" as used above shall mean this statement and includes all details or manufacture contained herein respectively.

Code: U	Contract: NASw-114
---------	--------------------

## FOREWORD

This quarterly report is submitted to the Office of Space Launch Vehicles of the National Aeronautics and Space Administration in accordance with the requirements of NASA Contract NASw-114.




## TABLE OF CONTENTS

SECTION	PAGE
Foreword	i
Table of Contents	iii
List of Figures	v
1 Introduction and Summary	1
2 Equipment	3
2.1 Test Loops	3
2.2 Temperature Control Calibration	5
2.3 Refrigeration System	11
2.4 Beam Port Shield	12
2.5 Remote Handling Equipment - Sample Change System	12
3 Flux Mapping	15
4 Testing Program	23
4.1 In-Pile Testing	23
4.2 Data Recording	29
4.3 Out-of-Pile Testing	29
Appendix A - Distribution	33

## LIST OF FIGURES

FIGURE		PAGE
1	Calibration Curve, Titanium Instrumented Specimen, Thermocouple #1	7
2	Calibration Curve, Titanium Instrumented Specimen, Thermocouple #2	8
3	Calibration Curve, Titanium Instrumented Specimen, Thermocouple #3	9
4	Correction Factors, Titanium Instrumented Specimen, Thermocouples #1, #2 and #3	10
5	Fast Neutron Flux Spectrum in HB-2 - Fuel Control Rods at Approximately 18" Position and at Full Forward Position	17
6	Measured Fast Neutron Flux Levels in HB-2 at Various Control Rod Positions	18
7	Fast Neutron Flux Level ( $E > 0.75$ Mev) in HB-2 as Function of Control Rod Position	20
8	Fast Neutron Flux Level ( $E > 0.5$ Mev) in HB-2 as Function of Control Rod Position	21
9	$\Phi > E/\Phi > 0.5$ Mev as Function of Neutron Energy	22
10	Typical Stress-Strain Diagram, Tensile Test Specimen	30





## 1 INTRODUCTION AND SUMMARY

17684 A

This report describes the progress made during the quarter, October through December 1963, on Contract NASw-114.

Investigation of the failure of nuclear instrumentation in the test loops continued during the period. A discussion of the failure is found in Section 2, Equipment. Temperature correlation measurements were obtained from an instrumented titanium test specimen.

Erratic behavior of the refrigeration system expansion engines is being evaluated.

The Mallory 1000 shield stud and plug were successfully modified by remote handling techniques.

Modification to the test loop carriages continued throughout the period. A new chevron seal, made of polyurethane, was conceived, designed and fabricated for the beam port.

Flux measurements were made in HB-2 reactor beam port at varying reactor operating conditions and different rod positions to better evaluate the time required to achieve an integrated dose of  $1 \times 10^{17}$  nvt fast neutrons ( $> 0.5$  Mev) for in-pile tests.

Both in-pile and out-of-pile test data were obtained on several materials during the period.

Author

## 2 EQUIPMENT

### 2.1 TEST LOOPS

The fission chambers in the test loops have not provided consistent measurement of the fast neutron flux due to the presence of moisture which reduced the resistance across the high voltage line to a level at which reliable readings could not be obtained. This moisture, in several instances, stemmed from water leaking into the stainless steel tubes carrying the instrument lines. The leaks were repaired and the tubes were evacuated to remove any residual moisture. The fission chamber tube was then filled with dry nitrogen and sealed. Repairs by this method proved satisfactory for eight (8) test cycles for one test loop; a second test loop became inoperative during the initial test cycle. In both instances, the fission chamber signal had become too erratic to be considered reliable. The indication is that other minute leaks in the stainless steel tubes have developed, admitting moisture to the instrument lines. All other instrumentation equipment continues to operate normally.

The malfunction of the fission chambers in the test loops necessitated other means of determining the integrated dose received by each test specimen. This was accomplished by using data from flux measurements obtained by the irradiation of foils with activation energies selected to provide the fast neutron flux level at the test position. These measurements were taken at various intervals during the reactor cycle. This method has been suitable so far since reactor core lattice configuration has been stable and flux distribution has not been influenced by the presence of other experimental equipment.

The polyurethane seals used in the joint between the test loop head assembly and the remainder of the test loop have withstood exposures to fast neutrons equivalent to an exposure as great as  $1.9 \times 10^{17}$  nvt at energy levels greater than 0.5 Mev at the test specimen position. It is interesting to note that while the sealing faces are serrated before irradiation, these surfaces are found to

be smooth after irradiation. The early seals, which were of cast gum, exhibited minor brittleness after exposure and minor swelling causing some difficulty in removal from the seal groove. The latest seals, made from millable gum stock, have exhibited greater swelling tendencies but are not brittle after irradiation. Both types of seals provide adequate sealing even though they have reduced strength as a result of irradiation.

Extensive experience has been gained in the remote specimen changing and minor repair techniques used on test loops in the hot cave. Thermocouple extension wires have been joined, instrument leads in the test loop head assembly repaired, Heli Coil inserts replaced, and a screw broken off below the surface of the head has been extracted using remote handling techniques. Equipment changes and repairs such as these have increased the utility value of the hot cave, and movement of the test loop to the hot laboratory area outside of the containment vessel for shop repairs has not been required as yet.

A line has been added to the test loop to provide continuous evacuation of the vacuum insulation annulus of the helium transfer lines within each loop. This line was added since, after several test cycles, it was noted that each loop was requiring increased refrigeration capacity to control specimen temperature. A temporary line was connected to a test loop to check the condition of the vacuum chamber, and the internal pressure was considerably higher than before irradiation. The lines were then evacuated continuously during the next several test cycles.

An increase of internal line pressure, during warm-up of the lines after removal of the loop from the beam port, followed by a decrease of internal pressure was observed. This action has not as yet been explained. However, the addition of a line to each loop to provide continuous evacuation during this period allows adequate control of the insulating vacuum.

## 2.2 TEMPERATURE CONTROL CALIBRATION

The sensing elements which control the specimen temperature are platinum resistance thermometers, which are quite sensitive to radiation damage. For this reason they are located out-of-pile on the inlet and outlet legs of the vacuum insulated refrigerant transfer lines that supply cold helium to the test loops. Since there is no direct measurement of the specimen temperature during testing, the temperature control system was correlated with a direct measurement of temperature at the test location. This correlation consisted of three steps: calibration of the direct measurement equipment, determination of the temperature distribution across the test specimen gage length, and determination of the correction to be applied to the control sensors to insure the 300°R temperature in the test specimens.

The procedure developed for each of these three steps was used in the preceding quarter establish temperature control conditions for stainless steel specimens. Since it was again used during the period covered by this report to establish control conditions for titanium alloy specimens, the method is briefly reviewed.

A test specimen, in this case a titanium alloy (6% Al 4% V) specimen, was instrumented with three copper-constantan thermocouples. These thermocouples, made from wire tested for homogeneity as outlined in Quarterly Report #7, Page 4, were attached at each end of the gage length and at the midpoint of the gage length, at positions shown in Figure 4 by the method described in Quarterly Report #7, Page 15.

In the first step, the calibration of these thermocouples, the instrumented specimen and a NBS calibrated resistance thermometer were included in a package wrapped in aluminum foil to provide a common temperature for the instrumented specimen and the resistance bulb reference standard. A fourth thermocouple, not included in the package, was used to measure environmental temperature. The package was placed in test loop 201-004 and the refrigeration system was used to provide a flow of cold helium around the package. The helium guides used during this

calibration were modified to accept the abnormal bulk of the package. The temperature of the test loop was stabilized at various levels between 30°R and 400°R while simultaneous recordings were made of the temperature measured with the resistance thermometer and the emf output of the thermocouples. An additional comparison of the thermocouples and the resistance thermometer was made by immersing the package in liquid nitrogen to check the test procedure at a known standard temperature. Calibration curves for the three specimen thermocouples are given in Figures 1, 2 and 3. Correction factors to convert the thermocouples' output to standard reference table emf values are given in Figure 4.

The second step in the procedure, the measurement of the temperature gradient across a titanium alloy (6% Al, 4% V) specimen, was done after the thermocouple calibration had been completed. For this measurement, the platinum resistance thermometer was removed allowing only the instrumented test specimen to remain in the test position in loop 201-004. The test loop temperature was stabilized in the 30°R range out-of-pile and the differential in temperature of the three thermocouple positions was recorded.

The forward thermocouple (TC-1) was 0.5°R colder than the midpoint thermocouple (TC-2) and 1.5°R colder than the aft thermocouple (TC-3). The loop was then inserted to the test position in beam port HB-2 during reactor operation to determine the effect of gamma heating on the specimen temperature distribution. After stabilization of the loop temperature in-pile, the forward thermocouple (TC-1) registered 4°R lower than the midpoint thermocouple (TC-2) and 5°R lower than the aft thermocouple (TC-3). This temperature spread is considered acceptable. During the in-pile testing program, the midpoint of the specimen gage length is maintained between 30°R and 31°R.

The final step in the calibration procedure, the establishment of temperature controller sensor readings which will insure a test specimen temperature of 30°R, was accomplished with the loop in-pile after the temperature distribution measurements had been




FIGURE 1 CALIBRATION CURVE FOR TITANIUM (6 Al, 2-1/2 Sn)  
INSTRUMENTED SPECIMEN THERMOCOUPLE NO. 1




FIGURE 2 CALIBRATION CURVE FOR TITANIUM (6 Al, 2-1/2 Sn)  
INSTRUMENTED SPECIMEN THERMOCOUPLE NO. 2




FIGURE 3 CALIBRATION CURVE FOR TITANIUM (6 Al, 2-1/2 Sn)  
INSTRUMENTED SPECIMEN THERMOCOUPLE NO. 3






FIGURE 4 CORRECTION FACTORS FOR TITANIUM INSTRUMENTED SPECIMEN THERMOCOUPLES 1, 2, & 3

completed. Under steady-state conditions, with refrigeration capacity balancing the gamma heating rate, the refrigeration control system temperatures were correlated with the emf output of the thermocouples located on the test specimen. This correlation is being applied to measured temperatures during in-pile testing.

### 2.3 REFRIGERATION SYSTEM

The operation of the refrigeration system during this period, after over 3000 hours of use, was somewhat erratic due to difficulties in the expansion engines. The first problem arose when the expansion engines could not be started after shut-down until the internal temperature had risen to about 400°R. The engines were removed, and it was found that oil had passed through the valve stuffing boxes and collected on the valve stems. When the valves were cold the oil became sufficiently viscous to prevent proper valve action. The oil was removed from the rods and the valve stuffing boxes were cleaned. The end cap was loose on three of the four intake valves making it necessary to replace these valves.

Later, erratic control of the expansion engines in engine pod #1 prompted a quite thorough investigation. Several leaks in the energy absorbing equipment were repaired and the pump was replaced as a means of eliminating possible contributing factors.

The valves again started to stick, causing difficulty in starting the engine until a temperature of 400°R had been reached. The valve stuffing was replaced in the valve stuffing boxes in both engine pods as it was felt that even after cleaning sufficient residual oil might be present in the valve stuffing to cause improper valve action.

A broken piston rod in an expansion engine later caused another operational delay. This rod had only 200 hours of operating time at failure. The failure occurred at the clamping position. All valve rods and remaining piston rods were ultrasonically inspected for possible internal discontinuities which might lead to failure. This inspection revealed no indications of incipient failure. A

broken exhaust valve spring, found during disassembly, was replaced when the unit was reassembled.

Further in-pile testing was accomplished with only the engines in engine pod #2 in operation. This decision was made since the test specimen temperature could be maintained using only engine pod #2. The behavior of the engines in pod #1 was still not considered sufficiently dependable to risk the loss of a test specimen in the event of a malfunction.

Present plans are to re-start the engines in pod #1 during the shutdown period which extends into the next reporting period and determine the cause for the erratic behavior of the engines so that all engines will be reliably operable during the next reactor cycle.

#### 2.4 BEAM PORT SHIELD

During this reporting period, the Mallory 1000 stud used to secure the shield plug was re-threaded to a 7/16-20 thread configuration by using remote handling techniques. This problem and proposed solution was discussed in Quarterly Progress Report #11, Page 4. A technique of applying a suitable nickel plating by a remote process was considered to be beyond the present state-of-the-art, in view of the fact that the original plating which had been applied under much more ideal conditions had not suitably adhered to the threaded portion of the Mallory 1000 material. Therefore, the stud was allowed to remain in the unplated condition.

The 3/4 inch thick Mallory 1000 shield plug was modified and installed on the re-threaded stud. All test operations to date have been accomplished with this plug in the shield.

#### 2.5 REMOTE HANDLING EQUIPMENT - SAMPLE CHANGE SYSTEM

Two test loop carriages have been modified to the design described in Quarterly Progress Report #11, Page 16. As a test

to assure adequacy of the design, both of these carriages were used to insert a test loop into the beam port five times against reactor system pressure without the reactor in operation. The carriages were then judged operational and used in actual in-pile tests. Components have been fabricated to assembly the remaining two carriages to the same design configuration.

The rubber chevron seals in the beam port have indicated a tendency to "roll" as a test loop is inserted. This causes severe damage to the three inner seals which are positioned so that they face outward. The force required to insert a test loop into the beam port is, in part, a function of the condition of the seals. Since the hydraulic pressure supplied to the motor is also a function of this force, an increase in the required hydraulic pressure required to drive a test loop into the beam port indicates deterioration of the seals, thus requiring a change. When it is necessary, these seals are changed by remote means. The use of polyurethane seals with thicker lips, in place of the present natural rubber seals, is being investigated as a means of obtaining a longer life expectancy.

Difficulties were encountered with the 10HP Clevite pump which operates the hydraulic system. One, which rendered the pump inoperative, was a failure of a valve spring after 171 operational hours. This pump was replaced with a similar 10HP pump on loan from the Clevite Corporation which operated during this period for 312 hours without mechanical failure. The other difficulty, a seal failure, was encountered earlier in the reporting period but did not cause shut-down. After a short period of operation, the seal which separates the lubrication system of the pump from the demineralized water hydraulic fluid failed, allowing an admixture of oil and high pressure water. The high pressure water forced the oil out of the pump crankcase, leaving only a residual film to provide lubrication. This seal failure occurred in both the regular pump and the pump on loan from the Clevite Corporation for operation during the repair of the failed valve spring. The pumps were kept in operation by refilling the crankcase frequently during use. The Clevite Corporation is investigating both incidents and hopes to provide remedial design corrections.

The present design of the system utilizes the 10HP Clevite pump to provide water to monitor leakage through the chevron seals at HB-2, thus requiring continuous operation while a test loop is in-pile. Since the in-pile exposure time required to accumulate an integrated dose of  $1 \times 10^{17}$  nvt on the test specimen is longer than originally contemplated, an auxiliary pressurizing system for the chevron seal is now being designed. In this sytem, a smaller pump will provide the pressure required at the chevron seal to prevent reactor primary water from mixing with quadrant water in the event of seal leakage. The 10HP Clevite pump will be required only for movement of the loops or transfer system. Since operation of the transfer system is now only a small fraction of irradiation time, this will greatly prolong the life of the Clevite pump.

The polyurethane seals in the 6" slide type gate valves used to shut off the beam port and the hot cave port, are still in excellent condition as far as can be determined by visual examination. The valves function properly with no evident leakage.

The hydraulic motors used on the carriages to drive the test loop into the beam port or hot cave port have functioned satisfactorily during operation to date, although an adequate seal to prevent water from leaking into the oil reservoir has also been a problem with these motors. Pressure forces most of the oil out of the reservoir but leaves a sufficient amount clinging to the components to provide adequate lubrication. One of the motors had previously been tested for an hour under full load conditions with no oil in the reservoir. There were no ill effects from this test; therefore, this condition is not considered to be detrimental. Operation to date has substantiated this conclusion. Bleed lines from the oil reservoir of each motor to a catch basic on the 0'-0" level have been installed to prevent oil contamination of quadrant water.

### 3 FLUX MAPPING

The spectral measurements of the fast neutron flux reported in Quarterly Report #11 were continued during this reporting period. The previous measurements indicated that the 3/4" Mallory 1000 shield plug would provide the most desirable fast neutron, thermal neutron and gamma population ratios. This shield plug was installed and has been in place during all flux mapping conducted during the reporting period.

Three sets of foils, as shown in Table 1, were used to obtain the fast flux spectrum at the test specimen position in HB-2 beam port. Each set of foils was irradiated for 30 minutes. They were then removed from the test loop and shipped by air to Georgia Nuclear Laboratories at Dawsonville, Georgia, where they were counted and evaluated in accordance with standard Lockheed techniques.

The results of these evaluations are presented in Figure 5. The curves in Figure 5 show a variation in flux level of approximately a factor of 2 at the 0.5 Mev neutron energy level. Examination of the condition of the several reactor operational variables at the time of the foil runs indicates that the change in flux level is a function of fuel control rod position.

These fuel control rods consist of cadmium encased in AISI Type 304 stainless steel in the upper portion. The lower portion consists of fueled segments of aluminum clad aluminum-enriched uranium alloy elements of the MTR type. The rods are progressively inserted into the core, from the bottom, during reactor operations, so as poison is removed from the core, fuel is added. One such rod is located in lattice positions LC-6, located directly in front of HB-2. This results in a rod shadowing effect and causes the significant variation in flux level.

To establish the fast neutron flux level as a function of fuel control rod position, five additional foil sets containing only  $\text{Np}^{237}$ ,  $\text{Th}^{232}$  and S foils were run at several rod positions. Figure 7 presents

TABLE 1

FOILS USED IN SPECTRAL MEASUREMENTS OF FAST NEUTRON FLUX IN HB-2

Type of Foil	Nominal Weight	Nuclear Reaction	Threshold Energy
Neptunium 237	20 micrograms	$^{237}\text{Np} (n, f) ^{140}\text{Ba}$	0.75 Mev
Thorium 232	50 micrograms	$^{232}\text{Th} (n, f) ^{140}\text{Ba}$	1.75 Mev
Sulfur	50 micrograms	$^{32}\text{S} (n, p) ^{32}\text{P}$	2.9 Mev
Nickel	0.1 gram	$^{58}\text{Ni} (n, p) ^{58}\text{Co}$	5 Mev
Magnesium	0.5 gram	$^{24}\text{Mg} (n, p) ^{24}\text{Na}$	6.3 Mev
Aluminum*	0.5 gram	$^{27}\text{Al} (n, d) ^{24}\text{Na}$	8.1 Mev

\* The  $^{27}\text{Al} (n, p) ^{27}\text{Mg}$  reaction with a threshold energy of 5.3 Mev is not included due to the short (9.8 m) half life of the product.




FIGURE 5 FAST NEUTRON FLUX MEASUREMENTS AT TEST SPECIMEN POSITION IN HB-2 BEAMPORT






FIGURE 6 FAST NEUTRON FLUX MEASUREMENTS AT TEST SPECIMEN POSITION IN HB-2 BEAM PORT

the flux level at 0.75 Mev, measured with the  $\text{Np}^{237}$  foils, as a function of control rod position. Figure 8 presents the flux level at 0.5 Mev, extrapolated from the foil curves, as a function of control rod position.

Since the fission chambers on loops 201-002 and 201-003 became inoperative due to water damage during this reporting period, the fast neutron dose received by the test specimen was determined by calculation based on the  $\phi_f$  obtained from Figure 8, the reactor power level, and irradiation time.

The control rod positions are recorded in the reactor operations log on an hourly basis. With this rod position the neutron flux per  $\text{cm}^2/\text{sec}/\text{watt}$  is obtained from Figure 8. The reactor power level is also available on an hourly basis so that the hourly incremental increase in the dose received by the test specimen is obtained from calculations made by using these factors. The results of the calculation are adjusted for each change in a parameter until the specimen has received an integrated dose of  $10^{17}$  nvt ( $> 0.5$  Mev) at which time the tensile load is applied to the specimen.

Examination of the test data presented elsewhere in this report shows that several specimens were exposed to integrated neutron fluxes somewhat in excess of  $1 \times 10^{17}$  nvt, due to in-pile exposure time calculations based on incomplete foil data.

Additional foil runs will be made during Cycle 10P and 11P, in the next quarter, to establish additional points on the high slope portion of the curve in Figure 8.

Figure 9, a curve presenting the ratio of the flux with a neutron energy level greater than 0.5 Mev to fluxes of other energy levels, is given as a base of comparison of NASw-114 test data with data from other sources.




FIGURE 7 FAST NEUTRON FLUX AT TEST SPECIMEN POSITION  
IN HB-2 VERSUS FUEL CONTROL ROD POSITION




FIGURE 8 FAST NEUTRON FLUX AT TEST SPECIMEN POSITION  
IN HB-2 VERSUS FUEL CONTROL ROD POSITION




FIGURE 9  $\Phi > E / \Phi > .5 \text{ MEV}$  AS A FUNCTION OF NEUTRON ENERGY

## 4 TESTING PROGRAM

### 4.1 IN-PILE TESTING

The first in-pile tests at 30°R were conducted during the period covered by this report. The material selected for the initial in-pile testing was AISI Type 304 stainless steel. This is the principal structural material used in the manufacture of the experiment's test loops and it was deemed advisable to determine the possibility of deleterious radiation effects on this alloy before the loops had acquired an extensive history of exposure in a high neutron environment. Although ductility measurements are not as yet available, the results of the in-pile testing of AISI Type 304 indicate, as expected, that it is probably a suitable material for this type of nuclear application.

The number of in-pile tests presently required by NASw-114 on AISI Type 304 were completed during this reporting period. The necessity of in-pile tests of additional specimens will be determined after the final data analysis has been made. The out-of-pile tests on this alloys had been completed at an earlier date and were reported in Quarterly Report #9. The results of in-pile tests and a summary of all test results obtained on AISI Type 304 stainless steel are given in Tables 2 and 3. Ductility measurements are not available at this time. Due to the wide scatter of the in-pile tensile notch results, additional testing will be undertaken on this type of specimen during the ensuing quarter.

The large increase (150%) of ultimate tensile strength coupled with the relatively modest increase (18%) of tensile yield strength in AISI Type 304 tensile specimens tested at 30°R out-of-pile from the room temperature properties is consistent with published data for this alloy. The radiation induced hardening resulting from exposure to a neutron environment increased the ultimate tensile strength 9% and the tensile yield strength 24% at 30°R.

The tensile notch specimen showed an increase of 57% in ultimate tensile strength between room temperature and 30°R. The increase

TABLE 2  
TEST DATA FOR AISI TYPE 304 STAINLESS STEEL (2 Cb) - MINIATURE TENSILE TESTS

Specimen Number	Test* Temperature (°R)	Total Accumulated Fast Neutron Dose (nvt)	Ultimate Tensile Strength (F <sub>ty</sub> in psi)	Tensile Yield (2% offset) (F <sub>ty</sub> in psi)	Elongation (% in 1/2")
2 Cb 229	30	1.8 x 10 <sup>17</sup> **	258, 000	53, 600	***
2 Cb 265	30	1.9 x 10 <sup>17</sup> **	259, 000	52, 200	***
2 Cb 245	30	1.9 x 10 <sup>17</sup> **	267, 000	53, 300	***
Average	-	-	261, 000	53, 000	***
Scatter	-	-	±1.7%	±1.3%	***
Test Conditions			Average Ultimate Tensile Strength (F <sub>tu</sub> in psi)	Average Tensile Yield Strength (0.2% offset) (F <sub>ty</sub> in psi)	Average Elongation (% in 1/2")
Room Temp., Out-of-pile			95, 200	36, 800	80
30°R, Out-of-pile			239, 800	42, 700	36
30°R, In-pile*			261, 000	53, 000	***

\* See Section 2.2, Page 5, for method of temperature control.

\*\* Overexposure due to lack of accurate flux data at time of test.

\*\*\* Not currently available.

TABLE 3

TEST DATA FOR AISI TYPE 304 STAINLESS STEEL (2 Cb)  
MINIATURE TENSILE NOTCH TESTS

Specimen Number	Test Temperature* (°R)	Total Accumulated Fast Neutron Dose (nvt)	Ultimate Tensile Strength (F <sub>tu</sub> in psi)
2 Cb 292	30	$1 \times 10^{17}$	203,000
2 Cb 295	30	$1.4 \times 10^{17}$ **	157,000
2 Cb 269	30	$1.12 \times 10^{17}$ **	228,000
Average	-	-	196,000***
Scatter	-	-	±20%
Test Conditions		Average Ultimate Tensile Strength (F <sub>tu</sub> in psi)	
Room Temp., Out-of-pile		106,300	
30°R, Out-of-pile		167,600	
30°R, In-pile		196,000****	

\* See Section 2.2, Page 5, for method of temperature control.

\*\* Overexposure due to lack of accurate flux data at time of test.

\*\*\* Due to wide scatter, additional tests will be performed and reported at a later date.

\*\*\*\* This value subject to revision based on additional tests to be undertaken at a later date.



in tensile strength caused by radiation induced hardening at 30°R was found to be 16%. However, the average in-pile test results will be further evaluated after additional tests have been performed to explain or reduce the excessively wide scatter band of the test data.

The second material selected for testing during the in-pile screening program was AISI Type 347 stainless steel. This was considered a suitable material for testing in conjunction with AISI Type 304 since both materials are modifications of the same basic alloy. Tensile testing of the AISI Type 347 was completed during this report period; one tensile notch test is still pending and will be completed in the next quarter. The out-of-pile tests on this alloy had been completed at an earlier date and reported in Quarterly Report No. 9. The results of the in-pile tests and a summary of all results obtained on AISI Type 347 stainless steel are given in Tables 4 and 5. As previously stated, ductility measurements are not as yet available and will be reported at a later date.

The results of the tensile tests are consistent with the results of tensile tests of AISI Type 304. The increase in ultimate tensile strength out-of-pile at 30°R was 151% and the increase due to radiation effects at 30°R was 5.6%. The increase in yield strength out-of-pile at 30° was 16% and the radiation induced hardening increased this value at 30°R by 21%.

The tensile notch specimen showed an increase in ultimate tensile strength of 100% at 30°R out-of-pile and a radiation induced increase of 7-1/2%, based on the incomplete results available at the end of this reporting period.

Designation of a mechanism to account for the magnitude of the changes in mechanical properties in these austenitic stainless steels must be deferred until the elongation and reduction of area measurements are available, as the existence of any significant change in ductility is of considerable important in the formulation of such a model.

TABLE 4

TEST DATA FOR AISI TYPE 347 STAINLESS STEEL (4 Cb) - MINIATURE TENSILE TESTS

Specimen Number	Test* Temperature (°R)	Total Accumulated Fast Neutron Dose (nvt)	Ultimate Tensile Strength (F <sub>ty</sub> in psi)	Tensile Yield (.2% offset) (F <sub>ty</sub> in psi)	Elongation (% in 1/2")
4 Cb 39	30	$2.1 \times 10^{17}$ **	277,000	69,000	****
4 Cb 43	30	$1.05 \times 10^{17}$	230,000	61,000	****
4 Cb 44	30	$0.93 \times 10^{17}$ ***	246,000	59,200	****
Average	-	-	251,000	63,000	****
Scatter	-	-	± 9.5%	± 8%	****
Test Conditions		Average Ultimate Tensile Strength (F <sub>tu</sub> in psi)	Average Tensile Yield Strength (0.2% offset) (F <sub>ty</sub> in psi)	Average Elongation (% in 1/2")	
Room Temp., Out-of-pile		94,400	44,900	58	
30°R, Out-of-pile		237,700	52,200	42	
30°R, In-pile*		251,000	63,000	****	

\* See Section 2.2, Page 5, for method of temperature control.

\*\* Overexposure due to lack of accurate flux data at time of test.

\*\*\* Exposure terminated due to irrecoverable reactor scram.

\*\*\*\* Not currently available.

TABLE 5

TEST DATA FOR AISI TYPE 347 STAINLESS STEEL (4 Cb)  
MINIATURE TENSILE NOTCH TESTS (INCOMPLETE)

Specimen Number	Test Temperature* (°R)	Total Accumulated Fast Neutron Dose (nvt)	Ultimate Tensile Strength (F <sub>tu</sub> in psi)
4 Cb 27	30	$1.18 \times 10^{17}$	244, 000
4 Cb 54	30	$1.19 \times 10^{17}$	265, 000
Average (2 only**)	-	-	254, 500
Scatter	-	-	± 8.5%
Test Conditions		Average Ultimate Tensile Strength (F <sub>tu</sub> in psi)	
Room Temp., Out-of-pile		112, 900	
30°R, Out-of-pile		227, 000	
30°R, In-pile*		254, 500	

\* See Section 2.2, Page 5, for method of temperature control.

\*\* One additional specimen will be tested during Reactor Cycle 10P.

#### 4.2 DATA RECORDING

A typical stress-strain diagram recorded during the in-pile testing of the austenitic stainless steel at 30°R is shown in Figure 10. This curve was obtained from an AISI Type 347 sample tested in-pile at 30°R.

Due to design limitations, the extensometers used for strain measurement during tensile testing have a reliably accurate operating range of only approximately 0.010 inch which is 2% of the 0.500" specimen gage length. This is sufficient to provide automatic recording on the X-Y plotter of the elastic portion of the stress-strain curve and a segment of the plastic portion, the extent of which is dependent on the modulus slope but cannot exceed 2% total strain. For this reason, a complete stress-strain diagram from application of the load to failure cannot be obtained with project equipment; after 2% total strain, only stress is recorded. Fluctuations of stress during testing which occur after the extensometer no longer measures strain are recorded by manual manipulation of the X axis pen and the abscissa divisions between stress variations are arbitrary and not related to strain.

In in-pile testing of austenitic stainless steels, considerable fluctuation of stress level was observed during the portion of the tests in which strain was not recorded. The irregular segment in the left side of Figure 10 shows the number and stress magnitude of these events. Complete stress-strain curves for austenitic stainless steel tested at cryogenic temperatures in the NBS Cryogenic Engineering Laboratory at Boulder, Colorado, (NBS PB 171809-3, Dec. 1961) show similar stress fluctuations during plastic behavior, so this phenomenon has been encountered in cryogenic environments and it is not as yet known if irradiation has any effect on the number or size of these stress fluctuations.

#### 4.3 OUT-OF-PILE TESTING

During the period covered by this report, out-of-pile testing was resumed on a limited basis. This testing was principally performed





FIGURE 10 STRESS-STRAIN DIAGRAM OF TENSILE SAMPLE

in test loops inserted in the hot cave with specimen changes accomplished by remote handling to provide operator training and allow refinement of remote tooling and techniques. The primary purpose of the resumption of out-of-pile testing at this time was training rather than rapid generation of test data. Scheduling of out-of-pile tests was restricted by access to the hot cave and availability of otherwise uncommitted training personnel. As a result of this approach, the requisite out-of-pile tests have not been completed for any of the new materials.



APPENDIX A  
DISTRIBUTION

William House  
NERVA Project Manager  
Aerojet-General Corporation  
P. O. Box 296  
Azusa, California

C. C. Ross  
Vice President, General Manager  
Nucleonics Division  
Aerojet-General Corporation  
San Ramon, California

Wayne Stinnett  
NERVA Project  
Aerojet-General Corporation  
P. O. Box 296  
Azusa, California

C. N. Trent  
Associate Director  
NERVA Operations  
Aerojet General Corporation  
P. O. Box 296  
Azusa, California

George Schult  
Allegheny Ludlum Steel Corp.  
Birmingham, Alabama

Edwin H. Spuhler  
Aluminum Company of America  
P. O. Box 1012  
New Kensington, Pa. 15068

T. H. Blewitt  
Argonne National Laboratories  
P. O. Box 299  
Lemont, Illinois

Argonne National Laboratories  
Information Center  
P. O. Box 299  
Lemont, Illinois

J. H. Kittel  
Argonne National Laboratories  
9700 South Cass Avenue  
Argonne, Illinois

D. J. McPherson  
Vice President  
IIT Research Institute  
10 W. 35th Street  
Chicago 16, Illinois

Arnold Engineering  
Development Center  
Information Center  
Tullahoma, Tennessee

Arthur D. Little, Inc.  
1424 Fourth Street  
Attn: Dorothy Crowder  
Santa Monica, California



Radiation Effects Information  
Center

Battelle Memorial Institute  
Attn: E. N. Wyler  
505 King Avenue  
Columbus 1, Ohio

Roger J. Runck  
Battelle Memorial Institute  
Columbus 1, Ohio

Beech Aircraft Corporation  
Technical Library  
P. O. Box 631  
Boulder, Colorado 80301

T. A. Rupprecht  
Library Services  
Bendix Corporation  
Research Laboratory Division  
Southfield, Michigan

Bendix Systems Division  
Librarian  
3300 Plymouth Road  
Ann Arbor, Michigan 48107

Boeing Airplane Company  
Information Center  
Seattle, Washington

D. H. Gurinsky  
Brookhaven National Laboratory  
Upton Long Island, New York 11973

Paul W. Levy  
Department of Physics  
Brookhaven National Laboratory  
Upton Long Island, N. Y. 11973

California Institute of  
Technology  
General Library  
1201 East California Street  
Pasadena, California 91109

University of California  
Librarian  
Berkeley, California

Lawrence Radiation Laboratory  
University of California  
Technical Information Division  
Berkeley, California

University of California  
Engineering & Mathematical  
Sciences Library  
Los Angeles 24, California

E. P. Eaton  
Carbone Company  
Toonton, New Jersey

Neil J. Culp  
Carpenter Steel Company  
P. O. Box 662  
Reading, Pennsylvania

University of Chicago  
Metal Institute Information  
Center  
Chicago, Illinois

K. D. Timmerhaus  
Associate Dean of Engineering  
University of Colorado  
Boulder, Colorado

Henry R. Dvorak, Director  
Nuclear Research & Development  
General Dynamics  
P. O. Box 748 - Plant Zone Y71  
Fort Worth, Texas

Convair, General Dynamics  
Information Center  
Fort Worth, Texas

Douglas Aircraft Company, Inc.  
A260 R & D Library  
3000 Ocean Park Boulevard  
Santa Monica, California

Commanding Officer  
Picatinny Arsenal  
Technical Information Section  
SMUPA-VA6  
Dover, New Jersey 07801

Department of the Army  
United States Army Munitions  
Command  
Frankford Arsenal - Librarian  
Philadelphia 37, Pennsylvania

General Electric Company  
ANPD Information Center  
Evendale, Ohio

General Electric Company  
Defense Electronics Division  
Attn: John Hannabach,  
Room 2434, Plant #2  
100 Plastics Avenue  
Pittsfield, Massachusetts

Georgia Institute of Technology  
Library  
Atlanta, Georgia 30332

University of Georgia Libraries  
Acquisitions Division  
Athens, Georgia 30601

E. B. Fernsler  
International Nickel Co., Inc.  
Huntington Alloy Products Div.  
Huntington 17, West Virginia

Knolls Atomic Power Lab.  
Document Librarian  
P. O. Box 1072  
Schenectady, New York

Lawrence Radiation Laboratory  
Technical Information Division  
University of California  
Attn: C. G. Craig  
P. O. Box 808  
Livermore, California

Charles A. Schulte  
Arthur D. Little Co., Inc.  
Acorn Park  
Cambridge, Massachusetts

P. M. Riede  
Union Carbide Corporation  
Linde Division  
P. O. Box 44  
Tonawanda, New York 14152

Dr. Lewis Larmore  
Chief Scientist  
Lockheed-California Company  
Burbank, California 91503

Central Library, Bldg. 63  
Scientific and Technical  
Information Center  
Lockheed-California Company  
Burbank, California

H. B. Wiley  
Engineering Research  
Lockheed-California Company  
Burbank, California

John C. McDonald  
Materials Research Staff  
Lockheed Missiles & Space Co.  
3251 Hanover Street  
Palo Alto, California

H. F. Plank  
Nucler Space Programs  
Lockheed Missiles & Space Co.  
Sunnyvale, California

Sci-Tech Information Center  
Lockheed Missiles & Space Co.  
Palo Alto, California

M. A. Steinberg, 52-30, 201  
Lockheed Missiles & Space Co.  
3251 Hanover Street  
Palo Alto, California

Frank Durham  
Los Alamos Scientific Lab.  
Los Alamos, New Mexico 87544

Glen A. Graves  
Los Alamos Scientific Lab.  
Los Alamos, New Mexico 87544

Los Alamos Scientific Lab.  
Report Library  
P. O. Box 1663  
Los Alamos, New Mexico 87544

George C. Marshall Space  
Flight Center  
Information Center  
Huntsville, Alabama 35812

W. Y. Jordan, P & VE - FN  
George C. Marshall Space  
Flight Center  
Huntsville, Alabama 35812

Dr. W. R. Lucas, M-P & VE-M  
George C. Marshall Space  
Flight Center  
Huntsville, Alabama 35812

R. D. Shelton, M-RP-N  
George C. Marshall Space  
Flight Center  
Huntsville, Alabama 35812

William T. White, M-ASTR-TSN  
Guidance & Control Division  
George C. Marshall Space  
Flight Center  
Huntsville, Alabama 35812

Ralph A. Wiles  
The Martin Company  
P. O. Box 1176  
Denver 1, Colorado

F. R. Schwartzberg, L-8  
The Martin Company  
P. O. Box 179  
Denver, Colorado

Robert G. Carter  
University Library  
University of Michigan  
Ann Arbor, Michigan 48104

L. C. Corrington  
Assistant Chief for Technical  
Operations  
National Aeronautics & Space  
Administration  
Space Nuclear Propulsion Office  
21000 Brookpark Road  
Cleveland 35, Ohio

George Deutsch  
National Aeronautics & Space  
Administration  
Code RRM  
Washington, D. C. 20546

M. H. Krasner  
National Aeronautics & Space  
Administration  
Lewis Research Center  
M & S Building  
21000 Brookpark Road  
Cleveland 35, Ohio

Harold B. Finger, Chief  
Space Nuclear Propulsion Office  
National Aeronautics & Space  
Administration  
Washington, D. C.

Scientific & Technical Information  
Facility  
Attn: National Aeronautics &  
Space Administration  
Representative (CRT)  
P. O. Box 5700  
Bethesda, Maryland 20014

George Mandel, Librarian  
National Aeronautics & Space  
Administration  
Lewis Research Center  
21000 Brookpark Road  
Cleveland 35, Ohio

Technical Information Center  
Rockedyn Division  
North American Aviation  
6633 Canoga Avenue  
Canoga Park, California

F. E. Farhat, Librarian  
Atomics International  
P. O. Box 309  
Canoga Park, California

Northrop Aircraft, Inc.  
Information Center  
Hawthorne, California

D. S. Billington  
Oak Ridge National Laboratory  
Oak Ridge, Tennessee 37831

Ralph R. Coltman, Jr.  
Oak Ridge National Laboratory  
Oak Ridge, Tennessee 37831

U. S. Atomic Energy  
Commission  
Division of Technical  
Information Extension  
P. O. Box 62  
Oak Ridge, Tennessee 37831

Ohio State University Libraries  
Serial Division  
1858 Neil Avenue  
Columbus, Ohio 43210

Purdue University  
Librarian  
Lafayette, Indiana

Mr. Joseph Marin  
Engineering Mechanics Dept.  
Pennsylvania State University  
105 Hammond Building  
University Park, Pa. 16802

Robert Paxon  
Pure Carbon Company  
Wellsville Street  
Saint Marys, Pennsylvania

L. E. Householder  
Reynolds Metals Company  
6601 West Broad Street  
Richmond, Virginia

The Fondren Library  
Rice University  
P. O. Box 1892  
Houston, Texas 77001

J. R. Kattus  
Southeastern Research Institute  
Birmingham, Alabama

Robert Neilsen  
Special Metals, Inc.  
New Hartford, New York

Space Technology Libraries, Inc.  
STL Technical Library  
One Space Park  
Redondo Beach, California

F. C. Schwenk  
United States Atomic Energy  
Commission  
Space Nuclear Propulsion Office  
Germantown, Maryland

Robert J. Torxell, Capt., USAF  
Air Force Rocket Propulsion  
Laboratory  
Attn: DGRSS  
Edwards, California 93523

Technical Librarian  
Kirtland Air Force Base  
Air Force Special Weapons  
Center  
Albuquerque, New Mexico

Cryogenic Data Center  
National Bureau of Standards  
Boulder, Colorado 80302

R. P. Reed  
Cryogenic Engineering Lab.  
U.S. Dept. of Commerce  
National Bureau of Standards  
Boulder, Colorado

John D. Peters, Lt. Col., USAF  
Chief, Space Systems Office  
(AEX) AEDC  
Arnold AFS, Tennessee 37389

Capt. J. H. Terry, RRNU  
Bureau of Naval Weapons  
Washington 25, D. C.

T. F. Kearns  
Bureau of Naval Weapons  
Washington 25, D. C.

Dr. Albert V. H. Masket  
Code 6204  
Mechanics Division  
U.S. Naval Research Lab.  
Washington, D. C. 20390

Waldo Rall  
United States Steel Corp.  
Monroeville, Pennsylvania

T. S. DeSisto  
U.S. Army Materials Research  
Agency  
Watertown Arsenal  
Watertown, Massachusetts

Dorothy W. Weeks  
AMRA  
Watertown Arsenal  
Watertown, Massachusetts

Dr. D. E. Thomas, Manager  
Materials Department  
Westinghouse Astronuclear Lab.  
P. O. Box 10864  
Pittsburgh 36, Pennsylvania

W. T. Wessel  
Westinghouse Electric Corp.  
Metallurgical Division  
Pittsburgh, Pennsylvania

Wright-Air Development Div.  
Information Center  
Wright-Patterson Air Force Base  
Dayton, Ohio

Alan R. Cole, Capt., USAF  
Foreign Technology Divisions  
TDEPR  
Wright-Patterson Air Force Base  
Dayton, Ohio

J. E. Morrissey  
Space Nuclear Propulsion Office  
United States Atomic Energy  
Commission  
Germantown, Maryland

Spencer Bush  
Hanford Atomic Products  
Operation  
General Electric Company  
Richland, Washington

E. F. Erbin, Staff  
Titanium Metals Corporation  
of America  
233 Broadway  
New York City, New York

David Novik, Chief (Code RN)  
National Aeronautics & Space  
Administration  
Washington, D. C. 20546

Technical Librarian  
SANDIA Corporation  
Albuquerque, New Mexico

C. A. Schwanbeck  
Lockheed-Georgia Company  
P. O. Box 2155  
Sandusky, Ohio

Mary G. Brown, Librarian  
Kaman Nuclear Division  
Kaman Aircraft Corporation  
Colorado Springs, Colorado

Thomas Harper  
National Aeronautics & Space  
Administration  
Code BCA  
Washington, D. C. 20546

Dr. A. M. Liebschutz  
Hughes Aircraft Company  
Nucleonics Division  
Fullerton, California

Harry M. Snowball  
AFFDL (FDCL)  
Wright-Patterson Air Force Base  
Dayton, Ohio

Dr. M. M. Miller, Manager  
Nuclear Aerospace Division  
Lockheed-Georgia Company  
86 South Cobb Drive  
Marietta, Georgia

B. P. Helgeson, Chief  
SNPO-N  
Nuclear Rocket Development  
Station  
Mercury, Nevada

A. Hurlich, Manager  
Materials Research Division  
Convair Astronautics  
San Diego, California

Air Force Materials Laboratory  
Research and Technology Div.  
AFSC  
Wright Patterson Air Force  
Base, Ohio 45433  
Attn: Harold H. Hormann